

Technical Problems with TCB Filings

Rich Fabina
Chief, Equipment Authorization Branch

Federal Communications Commission
Office of Engineering and Technology
Laboratory Division



Technical Problems with TCB Filings

- ➤ Part 15 Devices
 - General Issues
 - Device Specific Issues
 - RF Safety Issues
- Licensed Devices
 - General Issues
 - Device Specific Issues
 - RF Safety Issues
- > TCB Excluded Devices

October 13-15, 2004

TCB Workshop



- ➤ General Issues
 - Section 15.203 Compliance
 - Profession Installation not justified or missing
 - See interpretation 20011004-002
 - Intended use, installation requirements & marketing method
 - Unique antenna connector
 - · Permanently connected antenna
 - Section 15.204 Compliance (except 15.247)
 - Amplifier system approved together
 - Label on TX only

October 13-15, 2004

TCB Workshop

3



Part 15 Technical Problems

- ➤ General Issues (Cont'd)
 - Test Highest Gain Antenna/Highest Power Out
 - List approved antennas in filing
 - Provide photos of approved antennas
 - Describe output power selection/control
 - Type/length of cable when not provided
 - Ave. & Pk. Radiated Limits above 1 GHz
 - Comply with both limits
 - Conducted Power Listed on Grant
 - · ERP as grant note

October 13-15, 2004

TCB Workshop



- General Issues (Cont'd)
 - Pulsed Emissions meas. w/Ave. Detector
 - Measure w/Pk. detector & apply duty cycle
 - FCC ID Label on Battery Cover
 - Covers break off or are lost
 - Inconsistencies Throughout Most Filings
 - Output power, SAR/MPE distances, operational description, user manual
 - Multiple Transmitters/Modules
 - Transmit simultaneously?
 - · RF safety evaluation
 - EMC evaluation
 - Spurious/Intermod evaluation

October 13-15, 2004

TCB Workshop

5



Part 15 Technical Problems

- Device Specific Issues
 - Integral Antenna Requirement (15.407(d))
 - UNII device in 5.15-5.25 GHz band
 - Radiated Emissions Tested while Antenna Laying on Wood
 - Module w/cabled antennas
 - Mobile PCMICA Card w/Integral Antenna
 - Justification for not being portable device?
 - Used Wrong Limits for Harmonic Rad. Levels
 - 15.231 Fundamental determines limits for fund. & harm. Emissions

October 13-15, 2004

TCB Workshop



- Device Specific Issues (Cont'd)
 - Restricted Band (15.205) Freqs. Use 15.209
 Limits not 15.231 Limits
 - Emission in 15.205 Bands = RB = 15.209 limits
 - Band Edge Compliance @ 2.485 GHz (DTS)
 - Wide signal tuned to band edge will fail
 - Manual/Automatic Activated TX; Cease < 5 Sec.
 - 15.231(a)(1) & (2)
 - Rolling Codes
 - Pulses change w/each transmission
 - Duty cycle changes w/each transmission

October 13-15, 2004

TCB Workshop

7



Part 15 Technical Problems

- Device Specific Issues (Cont'd)
 - Maximize Emission Levels
 - Test in 3 orth. planes
 - Test at max. power
 - Test all accessories/devices
 - Site Must be 2.948 Listed for Part 15/18 Filings

October 13-15, 2004

TCB Workshop



- > RF Safety Issues
 - 20 cm is minimum Mobile Distance
 - MPE estimate not valid < 20 cm
 - Less than 20 cm. = SAR applies
 - Use Phantom of Correct Size
 - OET Bulletin 65, Sup. C, Annex D
 - Body Worn Statement Needed
 - Sup. C, Annex D
 - Describe Holster
 - Metal spring, distance from body, holds EUT forwards or backwards

October 13-15, 2004

TCB Workshop

9



Part 15 Technical Problems

- ➤ RF Safety Issues (Cont'd)
 - Inconsistent RF Safety Info
 - MPE/SAR distances in manual & tests
 - Power listed in oper. description & tests
 - SAR Test for Keyboard TX w/Screen Next to Phantom
 - Wrong SAR test distance used
 - Wrong face of device against phantom
 - List Head & Body SAR Values on Grant
 - Follow convention provided by FCC
 - MPE: Limits Wrong Tests Needed

October 13-15, 2004

TCB Workshop



- General Issues
 - Amplifier Guidelines Not Followed
 - See interpretation 20040310-001
 - Band edge Compliance Not Determined
 - Full power test @ band edge
 - Low & high channel too close to band edge for emission bandwidth
 - Conducted Measurements Missing
 - Output power, output spurious conducted, freq. stability, temp. stability, etc.

October 13-15, 2004

TCB Workshop

11



Licensed Problems

- ➤ General Issues (Cont'd)
 - Multiple Transmitter Evaluation
 - Simultaneous transmission capability?
 - TCBs can approve per 02 TCB Exc. List
 - MPE/SAR evaluation RF safety
 - EMC evaluation Spurious/intermod emissions
 - Power Exclusion in 2.1091 Exceeded
 - Routine evaluation required = MPE tests or computer simulation
 - AC Line Conducted Tests Don't Apply
 - 15.207 or 15.107 not applicable

October 13-15, 2004

TCB Workshop



- ➤ Device Specific Issues
 - 800/1900 MHz Non-US Functions Note Code Needed
 - This device contains 900/1800 MHz GSM functions that are not operational in U.S. territories. This filing is only applicable for...
 - Section 24.232(b) 2 W EIRP Limit Exceeded
 - Calculate EIRP w/power out & high antenna gain
 - Section 27.50©(2) 30 W ERP Limit Exceeded
 - Calculate ERP w/power out & high antenna gain

October 13-15, 2004

TCB Workshop

13



Licensed Problems

- Device Specific Issues (Cont'd)
 - Full Modular Approval for Portable Devices not available
 - Only limited modular approvals only
 - Device specific because SAR is device specific
 - Non-Voice Data Transmission in GMRS Prohibited
 - Section 95.631(f)

October 13-15, 2004

TCB Workshop



- > RF Safety Issues
 - List Head & Body SAR Values on Grant
 - Follow convention provided by FCC
 - List correct values
 - User Manual Info Missing/Inconsistent
 - · Hosts tested, accessories identified
 - · Non-metallic spring in holster
 - · Hand held use only
 - Grant Comment Wrong/Inconsistent
 - MPE/SAR distance, body worn Sup. C accessory limitation, non-metallic spring in holster

October 13-15, 2004

TCB Workshop

15



Licensed Problems

- > RF Safety Issues (Cont'd)
 - SAR Tested at Maximum Output Power
 - EUT in all modes/configurations too
 - Describe test conditions/software setup
 - Describe Holster Construction
 - Metallic or not
 - Hold EUT face and back to body of person
 - Provide Complete SAR Test Report
 - Provide Secondary SAR Hotspots

October 13-15, 2004

TCB Workshop



- RF Safety Issues (Cont'd)
 - User Manual Missing SAR Info
 - Number of Time Slots Used in Transmission
 - Affects SAR values
 - Lower SAR w/2 time slots vs. 1 time slot why?
 - Occupational Exposure Requirements Pt 90
 - Warning label on device
 - · Info in user manual
 - · Operational training to limit exposure

October 13-15, 2004

TCB Workshop

17



Licensed Problems

- RF Safety Issues (Cont'd)
 - MPE Evaluation Missing/Needed
 - Power exclusion in 2.1091 exceeded = MPE tests
 - Use correct MPE limit
 - SAR Tests Missing/Incomplete
 - SAR plots
 - SAR test set-up photos
 - Probe calibration data provided
 - Power drift conducted power vs. time for length of SAR tests provided

October 13-15, 2004

TCB Workshop



TCB Excluded Devices

- Devices Excluded from TCB Approval
 - Cell Phones w/HAC capability (Pt 22/24)
 - EPIRB Equipment (Pt 80)
 - Implanted Transmitters
 - Learned Transmitters (Pt 15)
 - MIMO & Smart Antenna Transmitters (Pt 15)
 - SDR
 - UWB (pt 15)
 - UNII w/DFS Capability (Pt15)

October 13-15, 2004

TCB Workshop

19



Summary

- ➤ Technical Problems with TCB Filings
 - Inconsistencies in Filings
 - Unfamiliar with Rules
 - Unfamiliar with Policies

October 13-15, 2004

TCB Workshop



Summary

- > Technical Problems with TCB Filings
 - What to do?
 - Carefully review test reports for inconsistencies & correct info before submission
 - Reread FCC Rules and review TCB training materials
 - Review material available from TCB council and FCC knowledge databases
 - When in doubt, ask the FCC; don't assume we will catch a mistake!

October 13-15, 2004

TCB Workshop

